


Clear Ballistics Re-Melting Instructions

For Metal Molds

Equipment Needed

- Constant heat source to maintain 250F to 270F
- Metal mold

1. *Remove all foreign material from gel.*
2. *Tear or cut gel into small pieces and place in mold.*
3. *Place mold into heat source such as oven or turkey roaster. If turkey roaster is used, please cover.*
4. *Heat for 4 hours or until all bubbles are gone from center of the gel.*
5. *Allow mold and gel to cool for at 12 hours.*
6. *After gel has cooled, remove gel by standing mold/gel on it's end, place hand between mold and gel while slowly pulling gel out.*



Clear Ballistics is not responsible for any damage that may occur during the re-melting process.